




How to update a communication driver?



When device is not registered at the I/O Device of CIMON-SCADA, User needs to register the Comm. driver manually.

1. Copy the given two Driver files “.dll” and “Driver.lst” into CIMON-SCADA installation folder.
2. Under CIMON-SCADA installation folder, double click on “Patch.exe” file. Driver dialog appear as shown below.



3. Click “OK” button to add the driver.